

ATTACHMENT I

**PHOTOS OF EXISTING CONDITIONS
MILLERTON ROAD & MARINA DRIVE**



Figure 1: Facing west on Millerton Road from Winchell Cove Road. Roadside pylons have been flattened or broken off completely by vehicles attempting to merge.



Figure 2: Winchell Cover Road meets Millerton Road, facing east from the northwest corner.

ATTACHMENT I

**PHOTOS OF EXISTING CONDITIONS
MILLERTON ROAD & MARINA DRIVE**



Figure 3: Facing north on Winchell Cove Road from Millerton Road.



Figure 4: Facing south across Millerton Road toward Marina Drive from Winchell Cove Road.

ATTACHMENT I

**PHOTOS OF EXISTING CONDITIONS
MILLERTON ROAD & MARINA DRIVE**



Figure 5: Facing west on Millerton Road with Marina Drive on the left (south) and Winchell Cove Road on the right (north).



Figure 6: Millerton road facing east toward Table Mountain's new casino.

ATTACHMENT I

**PHOTOS OF EXISTING CONDITIONS
MILLERTON ROAD & MARINA DRIVE**



Figure 7: Facing north across Millerton Road toward Winchell Cove Road from Marina Drive.



Figure 8: Facing west from the southeast corner of Marina Drive and Millerton Road.