

PHOTOS OF EXISTING CONDITIONS CARUTHERS TRANSPORTATION IMPROVEMENTS



Figure 1: East side of Kincaid Ave facing north from SE corner of Tahoe Ave & Kincaid Ave near high school.



Figure 2: West side of Kincaid Ave facing north from SW corner of Tahoe Ave & Kincaid Ave near high school.

PHOTOS OF EXISTING CONDITIONS CARUTHERS TRANSPORTATION IMPROVEMENTS



Figure 3: SE side of Tahoe Ave facing NE across from high school.



Figure 4: SE side of Tahoe Ave facing SW across from high school.

PHOTOS OF EXISTING CONDITIONS CARUTHERS TRANSPORTATION IMPROVEMENTS



Figure 5: SW side of Raider Ave facing NW from the SW corner of Sandy and Raider Ave near the fairgrounds.



Figure 6: NW side of Sandy facing SW from the SW corner of Sandy and Raider Ave near the fairgrounds.

PHOTOS OF EXISTING CONDITIONS CARUTHERS TRANSPORTATION IMPROVEMENTS



Figure 7: North side of Clemenceau Ave facing west near the elementary school.



Figure 8: Facing NE across Quince near NW entrance of the elementary school.

PHOTOS OF EXISTING CONDITIONS CARUTHERS TRANSPORTATION IMPROVEMENTS



Figure 9: SW side of Quince facing NW from the NW elementary school entrance.



Figure 10: NE side of Quince facing NW from the NW elementary school entrance.

PHOTOS OF EXISTING CONDITIONS CARUTHERS TRANSPORTATION IMPROVEMENTS



Figure 11: Superior Ave facing SW toward the fairgrounds.



Figure 12: Superior Ave facing NE from Raider Ave (fairgrounds).

PHOTOS OF EXISTING CONDITIONS CARUTHERS TRANSPORTATION IMPROVEMENTS



Figure 13: Raider Ave facing NW near the high school.



Figure 14: Raider Ave facing SE near the high school.