

PHOTOS OF EXISTING CONDITIONS EASTON SIDEWALK AND DRAINAGE IMPROVEMENTS



Figure 1: Student walking on buckled sidewalk on north side of Lincoln Ave near elementary school.



Figure 2: Student avoiding puddle on south side of Lincoln Ave near middle school.

**PHOTOS OF EXISTING CONDITIONS
EASTON SIDEWALK AND DRAINAGE IMPROVEMENTS**



Figure 3: Willamette facing east from Elm Ave.



Figure 4: South side of Willamette Ave facing west from Lily Ave at elementary school.

PHOTOS OF EXISTING CONDITIONS EASTON SIDEWALK AND DRAINAGE IMPROVEMENTS



Figure 5: West side of Lily Ave facing south at elementary school.



Figure 6: West side of Lily Ave facing north at elementary school.

PHOTOS OF EXISTING CONDITIONS EASTON SIDEWALK AND DRAINAGE IMPROVEMENTS



Figure 7: West side of Elm Ave facing south from Willamette Ave.



Figure 8: West side of Elm Ave facing north from Willamette Ave..

PHOTOS OF EXISTING CONDITIONS EASTON SIDEWALK AND DRAINAGE IMPROVEMENTS



Figure 9: West side of Elm Ave facing south from Fantz Ave.



Figure 10: West side of Elm Ave facing north from Fantz Ave.

PHOTOS OF EXISTING CONDITIONS EASTON SIDEWALK AND DRAINAGE IMPROVEMENTS



Figure 11: East side of Elm Ave facing south just south of Lincoln Ave.



Figure 12: East side of Elm Ave facing north from just south of Lincoln Ave.

**PHOTOS OF EXISTING CONDITIONS
EASTON SIDEWALK AND DRAINAGE IMPROVEMENTS**



Figure 13: South side of Lincoln Ave. facing west from Lily Ave.



Figure 14: North side of Lincoln Ave facing west from Geneva Ave.